

Pg. 1 of 7

MATERIAL SAFETY DATA SHEET

Version :01

PRODUCT NAME: E.D.T.A. N/50 (0.02 N) SOLUTION

CAS Number: **NA**

1. IDENTIFICATION:		
Product Code	: 90670	
Company Name	: ADVENT CHEMBIO PRIVATE LIMITED	
Address	W-279, MIDC, TTC INDUSTRIAL AREA, THANE-BELAPUR ROAD, RABALE, NAVI MUMBAI - 400 701.	
E-mail	: <u>sales@adventchembio.com</u>	
WEBSITE	: <u>www.adventchembio.com</u>	
Company Phone Number	: 022-27690837	

2. HAZARDS IDENTIFICATION:

Hazard classification		
Physical hazards		
Health hazards	hazardous substance or mixture according to Regu	lation
Labels elements	a hazardous substance or mixture according to Regu	lation
Hazard symbol	a hazardous substance or mixture according to Regu	lation
Signal word	a hazardous substance or mixture according to Regu	lation
Hazard statement	a hazardous substance or mixture according to Regu	lation
Precautionary statement		
Prevention	not breathe dust/ fume/ gas/ mist/ vapors/ spra autions have been read and understood. r protective gloves/ protective clothing/ eye protect away from heat/ sparks/ open flames/ hot surfaces	ion/ face protection.
Response	I SKIN (or hair): Rinse skin with water/ shower. EYES: Rinse with water for several minutes. Remove Continue rinsing. HALED: Remove person to fresh air and keep comfor /ALLOWED: Immediately call a POISON CENTER or d	rtable for breathing.
Storage	e in a dry & well-ventilated place. Keep container t ed must be carefully resealed and kept upright to p	•
Disposal	ose of contents/container to an appropriate to rdance with applicable laws and regulations, and osal.	reatment and disposal facility in
Other hazards which do not result in GHS classification	substance/mixture contains no components consi mulative and toxic (PBT), or very persistent and ve 1% or higher.	•



Pg. 2 of 7

MATERIAL SAFETY DATA SHEET

Version :01

PRODUCT NAME: E.D.T.A. N/50 (0.02 N) SOLUTION

CAS Number: NA

3. COMPOSITION/ INFORMATION ON INGRADIENTS:				
Ingredient	CAS Number	NORMALITY	Hazardous	
E.D.T.A. N/50 (0.02 N) Solution	NA	0.02 ± 0.005 N	No	
4. FIRST AID MEASURES:				
General information	: Get medical advice/attent attendance.	ion if you feel unwell. Show this sa	afety data sheet to the doctor in	
Ingestion	 Rinse mouth. Do NOT induce vomiting. If vomiting occurs, keep head low so that stomach content doesn't get into the lungs. Move to fresh air. Call a physician or poison control center immediately. If breathing stops, 			
Inhalation	 provide artificial respiration. If breathing is difficult, give oxygen. Get medical attention if symptoms persist. 			
Skin contact	Immediately flush with plenty of water for at least 15 minutes. If easy to do, remove contact lenses. Get medical attention.			
Eye contact	Immediately flush with plenty of water for at least 15 minutes. If easy to do, remove contact lenses. Get medical attention.			
Most important symptoms/effects, acute and delayed Indication of immediate	: Not a hazardous substance or mixture according to Regulation			
medical attention and special treatment needed	: Symptoms may be delayed	d. Treat symptomatically.		

5. FIRE FIGHTING MEASURES:

General information

Suitable (and unsuitable) extinguishing media

:

Suitable extinguishing media	:	Use water spray, alcohol-resistant foam, dry chemical or carbon dioxide.
Unsuitable extinguishing media	:	For this substance/mixture no limitations of extinguishing agents are given.
Specific hazards arising from the chemical	:	Nature of decomposition products not known.
Special protective equipment	t an	d precautions for firefighters
Special firefighting procedures	:	Use water spray to keep fire-exposed containers cool. Water may be ineffective in fighting the fire. Fight fire from a protected location. Move containers from fire area if you can do so without risk.
Special protective equipment for fire-fighters	:	Firefighters must use standard protective equipment including flame retardant coat, helmet with face shield, gloves, rubber boots, and in enclosed spaces, SCBA.

6. ACCIDENTAL RELEASE MEASURES:

Personal precautions,	:	ELIMINATE all ignition sources (no smoking, flares, sparks or flames in immediate area).
protective equipment and		Avoid breathing mists or vapors. Keep upwind. Ventilate closed spaces before entering



Pg. 3 of 7

MATERIAL SAFETY DATA SHEET

Version :01

PRODUCT NAME: E.D.T.A. N/50 (0.02 N) SOLUTION

CAS Number: NA

emergency procedures	them. Do not touch damaged containers or spilled material unless wearing appropriate
Methods and material for	protective clothing. Keep unauthorized personnel away. Eliminate all ignition sources if safe to do so. Use only non-sparking tools. Take
containment and cleaning	precautionary measures against static discharges. Stop leak if possible without any risk.
up	: Absorb spill with vermiculite or other inert material, then place in a container for chemical
	waste. Clean surface thoroughly to remove residual contamination. Dike far ahead of larger
Notification Procedures	spill for later recovery and disposal. Prevent entry into waterways, sewer, basements or confined areas. Inform authorities if
	large amounts are involved.
Environmental precautions	Do not contaminate water sources or sewer. Prevent further leakage or spillage if safe to do
	so. Avoid discharge into drains, water courses or onto the ground.
7. HANDLING AND STORAG	E:
Precautions for safe handling	Do not handle until all safety precautions have been read and understood. DO NOT handle, store or open near an open flame, sources of heat or sources of ignition. Protect material
nanuning	from direct sunlight. Take precautionary measures against static discharges. Ground/bond
	container and receiving equipment. Use explosion-proof
	electrical/ventilating/lighting/equipment. Use only non-sparking tools. Wear protective
	gloves/protective clothing/eye Protection / face protection. Avoid contact with eyes, skin, and clothing. Do not breathe
	mist or vapor. Use only with adequate ventilation. Wash hands thoroughly after handling.
Conditions for safe storage,	Keep away from food, drink and animal feeding stuffs.
including any	
incompatibilities	[:] Keep container tightly closed in a dry, well-ventilated place.
8. EXPOSURE CONTROLS PL	
8. EXPOSURE CONTROLS PI	RSONAL PROTECTION:
Control parameters	RSONAL PROTECTION:
Control parameters Occupational exposure	RSONAL PROTECTION:
Control parameters	RSONAL PROTECTION:
Control parameters Occupational exposure limits Appropriate engineering	ERSONAL PROTECTION: : No data available
Control parameters Occupational exposure limits Appropriate engineering controls	: No data available
Control parameters Occupational exposure limits Appropriate engineering controls	
Control parameters Occupational exposure limits Appropriate engineering controls	 No data available es, such as personal protective equipment Good general ventilation (typically 10 air changes per hour) should be used. Ventilation
Control parameters Occupational exposure limits Appropriate engineering controls Individual protection measur	 No data available es, such as personal protective equipment Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust
Control parameters Occupational exposure limits Appropriate engineering controls	 No data available es, such as personal protective equipment Good general ventilation (typically 10 air changes per hour) should be used. Ventilation
Control parameters Occupational exposure limits Appropriate engineering controls Individual protection measur	 No data available es, such as personal protective equipment Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation, or other engineering controls to maintain airborne levels below recommended exposure limits. If exposure limits have not been established, maintain airborne levels to an acceptable level. An eye wash and safety shower must be available in the immediate work
Control parameters Occupational exposure limits Appropriate engineering controls Individual protection measur General information	 No data available es, such as personal protective equipment Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation, or other engineering controls to maintain airborne levels below recommended exposure limits. If exposure limits have not been established, maintain airborne levels to an acceptable level. An eye wash and safety shower must be available in the immediate work area. Use explosion-proof ventilation equipment.
Control parameters Occupational exposure limits Appropriate engineering controls Individual protection measur	 No data available es, such as personal protective equipment Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation, or other engineering controls to maintain airborne levels below recommended exposure limits. If exposure limits have not been established, maintain airborne levels to an acceptable level. An eye wash and safety shower must be available in the immediate work
Control parameters Occupational exposure limits Appropriate engineering controls Individual protection measur General information	 No data available es, such as personal protective equipment Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation, or other engineering controls to maintain airborne levels below recommended exposure limits. If exposure limits have not been established, maintain airborne levels to an acceptable level. An eye wash and safety shower must be available in the immediate work area. Use explosion-proof ventilation equipment.
Control parameters Occupational exposure limits Appropriate engineering controls Individual protection measur General information Eye/face protection	 No data available es, such as personal protective equipment Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation, or other engineering controls to maintain airborne levels below recommended exposure limits. If exposure limits have not been established, maintain airborne levels to an acceptable level. An eye wash and safety shower must be available in the immediate work area. Use explosion-proof ventilation equipment. Wear safety glasses with side shields (or goggles).
Control parameters Occupational exposure limits Appropriate engineering controls Individual protection measur General information Eye/face protection Hand protection	 No data available es, such as personal protective equipment Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation, or other engineering controls to maintain airborne levels below recommended exposure limits. If exposure limits have not been established, maintain airborne levels to an acceptable level. An eye wash and safety shower must be available in the immediate work area. Use explosion-proof ventilation equipment. Wear safety glasses with side shields (or goggles). Chemical resistant gloves.
Control parameters Occupational exposure limits Appropriate engineering controls Individual protection measur General information Eye/face protection Hand protection Other	 No data available es, such as personal protective equipment Good general ventilation (typically 10 air changes per hour) should be used. Ventilation rates should be matched to conditions. If applicable, use process enclosures, local exhaust ventilation, or other engineering controls to maintain airborne levels below recommended exposure limits. If exposure limits have not been established, maintain airborne levels to an acceptable level. An eye wash and safety shower must be available in the immediate work area. Use explosion-proof ventilation equipment. Wear safety glasses with side shields (or goggles). Chemical resistant gloves. Wear suitable protective clothing.



Pg. 4 of 7

MATERIAL SAFETY DATA SHEET

Version :01

PRODUCT NAME: E.D.T.A. N/50 (0.02 N) SOLUTION

CAS Number: NA

	Respirator with organic vapor cartridge.
Hygiene measures	Always observe good personal hygiene measures, such as washing after handling th material and before eating, drinking, and/or smoking. Routinely wash work clothing an protective equipment to remove contaminants. Provide eyewash station and safety showe Avoid contact with eyes, skin, and clothing.
9. PHYSICAL AND CHEMICA	L PROPERTIES:
Appearance	: Clear colourless solution.
Odor	: No data available
Solubility	: Soluble in mixture of dilute ammonia and water.
Formula	: NA
Molecular Weight	: NA
Specific Gravity	: No data available
рН	: No data available
% Volatiles by volume @ 21C (70F)	: No data available
Boiling Point	: No data available
Melting Point	: No data available
Flash Point	: No data available
Vapor Density (Air=1)	: No data available
Vapor Pressure (mm Hg)	: No data available No data available
Evaporation Rate (BuAc=1)	
10. STABILITY AND REACTIVE	
Reactivity	No data available
Chemical stability	: Material is stable under ambient conditions
Possibility of hazardous reactions	No data available
Conditions to avoid	: No data available
Incompatible materials	No data available
Hazardous decomposition products	: In the event of fire: see section 5



Pg. 5 of 7

MATERIAL SAFETY DATA SHEET

Version :01

PRODUCT NAME: E.D.T.A. N/50 (0.02 N) SOLUTION

CAS Number: NA

11. TOXICOLOGICAL INFORM	MAT	ION:		
Information on likely routes of exposure				
Ingestion	:	No data available		
Inhalation	:	No data available		
Skin contact	:	No skin irritation		
Eye contact	:	Causes eye irritation		
Information on toxicological	effe	ects		
Acute toxicity (list all possib	le ro	utes of exposure)		
Oral Product	:	No data available.		
Dermal Product	:	No data available.		
Inhalation Product	:	No data available.		
Repeated dose toxicity Product	:	No data available.		
Skin corrosion/irritation Product	:	No data available.		
Serious eye damage/eye irritation Product	:	No data available.		
Respiratory or skin sensitization Product	:	No data available.		
Carcinogenicity Product	:	No ingredient of this product present at levels greater than or equal to 0.1% is identified as probable, possible or confirmed human carcinogen by IARC.		
IARC Monographs on the Evaluation of Carcinogenic Risks to Humans	:	No ingredient of this product present at levels greater than or equal to 0.1% is identified as probable, possible or confirmed human carcinogen by IARC.		
Germ cell mutagenicity				
In vitro Product	:	No data available.		
Reproductive toxicity Product	:	No data available.		
Specific target organ toxicity - single exposure	:	Not known.		
Product Specific target organ toxicity - repeated exposure Product	:	None known.		
Aspiration hazard Product	:	No data available.		
Other effects	:	None known.		



Pg. 6 of 7

MATERIAL SAFETY DATA SHEET

Version :01

PRODUCT NAME: E.D.T.A. N/50 (0.02 N) SOLUTION

CAS Number: **NA**

12. ECOLOGICAL INFORMATION:

Ecotoxicity	
Acute hazards to the aquati	c environment
Fish Product	: No data available.
Aquatic invertebrates Product	: No data available.
Chronic hazards to the aqua	itic environment
Fish Product	: No data available.
Aquatic invertebrates Product	: No data available.
Toxicity to Aquatic Plants Product:	: No data available.
Persistence and degradabili	ty
Biodegradation Product	: No data available.
BOD/COD ratio Product	: No data available.
Bioaccumulative potential	
Bioconcentration factor (BCF) Product	: No data available.
Partition coefficient n- octanol / water (log Kow) Product	: No data available.
Mobility in soil	: No data available.
Other adverse effects	: No data available.
13. DISPOSAL CONSIDERAT	ION:
Disposal instructions	: Discharge, treatment, or disposal may be subject to national, state, or local laws. Disposal
Contaminated packaging	recommendations are based on uncontaminated material. Since emptied containers retain product residue, follow label warnings even after container is emptied.

14. TRANSPORT INFORMATION:

DOT IMDG IATA	I	UN proper shipping name E.D.T.A. N/50 (0.02 N) Solution E.D.T.A. N/50 (0.02 N) Solution E.D.T.A. N/50 (0.02 N) Solution		Packaging group Not dangerous goods Not dangerous goods Not dangerous goods	
---------------------	---	---	--	---	--



Pg. 7 of 7

MATERIAL SAFETY DATA SHEET

Version :01


PRODUCT NAME: E.D.T.A. N/50 (0.02 N) SOLUTION

CAS Number: NA

15. REGULATORY INFORMATION:

This safety datasheet complies with the requirements of Regulation (EC) No. 1907/2006. Safety, health and environmental regulations/legislation specific for the substance or mixture No Data Available.

16. OTHER INFORMATION:



Issue Date	:	01/07/2023
Version	:	01

Disclaimer: This Material Safety Data Sheet (MSDS) is for guidance and is based upon information and tests believed to be reliable. ADVENT CHEMBIO PRIVATE LIMITED makes no guarantee of the accuracy or completeness of the data and shall not be liable for any damages relating thereto. The data is offered solely for your consideration, investigation, and verification. The data should not be confused with local, state, federal or insurance mandates, regulations, or requirements and CONSTITUTE NO WARRANTY. Any use of this data and information must be determined by the technical instructor in accordance with applicable local, state or federal laws and regulations. The conditions or methods of handling, storage, use and disposal of the product(s) described are beyond the control of ADVENT CHEMBIO PRIVATE LIMITED and may be beyond our knowledge. FOR THIS AND OTHER REASONS, WE DO NOT ASSUME RESPONSIBILITY AND EXPRESSLY DISCLAIM LIABILITY FOR LOSS, DAMAGE OR EXPENSE ARISING OUT OF OR IN ANY WAY CONNECTED WITH THE HANDLING, STORAGE, USE OR DISPOSAL OF THIS PRODUCT(S).